## Provided Hardware:



Replacement Cables

Suggested Hardware:



Replacement Zipties

## Suggested Tools:



Assembly:

Small Phillips Screwdriver



Begin by unplugging your station and placing it upside-down on a flat surface.



Remove the 4 Phillips head screws from the bottom.



## **Assembly Continued:**



The enclosure comes apart into 4 pieces. Place the main piece with the circuit board on a flat surface.



Locate the 2 ziptie pads that secure the cables. Cut them and remove the current charging cables.



Replace cables in correct order, re-secure new cables with new zipties and reconstruct the station. Replace the 4 screws making sure that each enclosure piece has no gaps.



Need more info?